






Dvoudveřová šatní skříň LINCOLN






3 / 1



3 / 2



3 / 3



13.07.01.110 x 16



13.07.01.108 x 16



13.01.01.111 x 16



M4X22
13.03.01.010 x 6



4X16
13.02.01.004 x 24



M6X13
13.03.01.021 x 1




13.07.01.076 x 8



M6X25
13.03.01.027 x 2




13.01.01.175 x 1




13.02.01.019 x 8



13.01.01.554 x 12
13.01.01.555 x 4



4X70
13.02.01.011 x 1



13.07.01.131 x 2




13.01.01.483 x 4




13.07.01.016 x 1




13.07.01.405 x 4



13.07.01.135 x 1




13.04.01.057 x 6




13.05.01.029 x 2


3/1




3/2




3/3




1




2




3




4



5




6




7

18.40.1001.001




8

18.40.1001.007




18.40.1001.008



9

18.40.1001.009 X2





10

18.40.1001.007




18.40.1001.009x1

18.40.1001.008

18.40.1001.009x1




11



4X16
13.02.01.004 X 4

13.05.01.029 X 2



12

13.02.01.019 x 4


13.07.01.016 x 1

13.01.01.483 x 4

18.40.1001.005

8 x

18.40.1001.006



13


13.07.01.016




M6X25

13.03.01.027 x 2


13.07.01.131 x 2

13.02.01.004 x 4
4X16







17




18




19




20



21



22



23

